



Ax2		Bx1	Cx1				Dx1				
			Ex1	Fx1	Gx1	Hx2	Ix2	Jx2	Kx1		
Lx1	Mx1	Nx4	Ox4	Px2	Qx20	Rx8	Sx16	Tx18	Ux18	Vx10	Wx1

1






(T) x2	(U) x2	(V) x2

2





(T) x8	(V) x8



3





4





5





6






7




8





9




10



11



12



13

