


COMPUTER TABLE

ASSEMBLY INSTRUCTION

Thanks for purchasing one of our products, please read carefully the assembly instructions before the installation (Attention: Do not tighten the screws before all screws are in place).





MODEL CT-3541

General Care:

-Keep your furniture out direct sunlight-Use desk pads and coasters to protect the surface from dents, scratches, and moisture from hot or cold liquids.


Cleaning:


- -For cleaning, wipe the surface with a damp (not wet) cloth or wipe dry with a clean lint free cotton cloth.
- -Window cleaning liquid or a similar cleaning liquid can be used to clean glass surface.

P. 2



PARTS LIST






-SCREWS LIST

PART	QTY.	ITEM	
Α	16	6X40 MM	
В	24	3X15 MM	Dunn
С	8	4X35 MM	Dunnun
D	8	6X15 MM	()
E	6	6X25 MM	(1)
F	8	6X30 MM	(i)
G	3	6X40 MM	

PART	QTY.	ITEM	
Н	2	6X65 MM	(i)
	8	Ф 16 ММ	0
J	2	M6	9
K	1	Ф 18 ММ	0
	1		
	1		5==3



■ 6X40MM BOLT INSTALLATION AS BELOW:



- ASSEMBLY STEPS:

